



Worldwide repairs carried out with PolymerMetal®

REP-# 046



Sealing of a cooling water pipe made of steel without switching off the plant. Cause of the damage was material fatigue. The repair was carried out with MM-metal UW with Hardener UW3 and MM-Fabric tape (glass fibre).

MultiMetall
the MetalExistenceCompany®