




Worldwide repairs carried out with PolymerMetal®

REP-# 102



Repair of a ship's turbocharger with VP 10-500. Scourings, cracks and apertures from the gas entrance to the cooling water side were repaired with VP 10-500. For the reinforcement two layers of MM-Fabric tape (glass fibre) were used.

MultiMetall
the MetalExistenceCompany®