

REP-# 104







An additional water-centrifugal pump being damaged by erosion and cavitation was rebuilt using Ceramium. Housing and flanged socket were coated inside with VP 10-017.

MultiMetall

the MetalExistenceCompany®