



Worldwide repairs carried out with PolymerMetal®

REP-# 106



A chrome plated hydraulic piston showed strong surface flaking. As there were thinnest layers and antifriction properties required, the repair was affected with Molymetal.

MultiMetal
the MetalExistenceCompany®