

**REP-#159** 





A damaged power transformer located in a steel plant has been repaired by using MM-metal oL-steelceramic and Hardener yellow.