


**REP-# 002** 



Sealing of an oil leak between the cover and diverter switch of a transformer with MM-Elastomer 95. First the oil in the transformer was drained and the surface thoroughly cleaned with MM-Degreaser Z. Finally MM-Elastomer 95 was applied using a brush.

## MultiMetall

the MetalExistenceCompany®