


REP-# 048



Repair of an automatic glass machine at a channel for broken glass and water. The coating procedure was affected in two steps - first application with Ceramium, pasty, followed by a second application with Ceramium, liquid. The previous reconstruction procedure was build-up welding.

MultiMetall

the MetalExistenceCompany®