


Worldwide repairs carried out with PolymerMetall®

REP-# 065



Ceramium with hardener CE was used to repair cracks and damages caused by erosion between cast segments at a gas washer (Venturi) of a blast furnace cleaning facility. Due to this the life of the component was doubled.

MultiMetall
the MetalExistenceCompany®