


REP-# 070



Repair of a bucket wheel excavator for the field of open-cast mining by applying Ceramium liquid. The main drive shaft of the bucket wheel rim, which was damaged due to abrasion, was reconstructed at a length of 400 mm with a diameter of 360 mm. The diameter has been reduced to 350 mm before the rebuilding.

MultiMetall

the MetalExistenceCompany®