



Worldwide repairs carried out with PolymerMetal®

REP-# 124



Repairing a corroded and worn out pillow block bedding of a steel sheet rolling line using MM-metal SS-steelceramic. The precise pillow block seat was obtained with the help of a metal plate.

MultiMetal
the MetalExistenceCompany®