




Worldwide repairs carried out with PolymerMetal®

REP-# 134



34 damaged back-up rolls bearing houses of a steel work's hot strip mill were modified. The above drawing shows a bearing shell which was damaged by turning of the outer bearing bore. Conventional repairs of these damages would have been executed by welding on, heat-treating and turning to original size. Cheaper and less time intensive is an innovative repair with MM-metal steelceramic and Hardener yellow.

MultiMetall
the MetalExistenceCompany®