


REP-# 135



34 damaged back-up rolls bearing houses of a steel work's hot strip mill were modified. The above drawing shows guiding plates as a fixture to the bearing house. To achieve a constant distance to the bearing at unchanged plate thickness, the surface damaged by erosion and mechanical load was restored by MM-metal steelceramic and Hardener yellow.

**MultiMetall**  
the MetalExistenceCompany®