




Worldwide repairs carried out with PolymerMetal®

REP-# 095



Repair of an undersized bronze propeller shaft: diameter appr. 380 mm, length appr. 6000 mm due to friction in the stuffing box. Material used: Ceramium with Hardener CE. After curing the propeller shaft was machined.

MultiMetall
the MetalExistenceCompany®