



*Worldwide repairs carried out with PolymerMetal<sup>®</sup>*

REP-# 120



Sealing of a cracked pump casing at reduced water outlet using MM-metal UW and Hardener UW3.

**MultiMetall**  
the MetalExistenceCompany<sup>®</sup>