




Worldwide repairs carried out with PolymerMetal®

REP-#147



In a mining plant the cost and time intensive new acquisition of a replacement shaft for a damaged shaft of a vibrating screen was prevented by the repair with MM-metal SS-steel.

MultiMetall
the MetalExistenceCompany®

MultiMetall • P.O. Box 12 02 64 • 41720 Viersen • Germany
Tel: +49 (0) 21 62-97 00 9-0 • Fax: +49 (0) 21 62-97 00 9-11
Email: info@polymermetal.com • Web: www.polymermetal.com