



*Worldwide repairs carried out with PolymerMetal®*

REP-#158



Several worn areas of a steel plant's leaky power transformer have been sealed with MM-metal oL-steelceramic and Hardener yellow.

**MultiMetal**  
the MetalExistenceCompany®